



**ROOF CONSULTING
SERVICES, INC.**

Estimated Cost (In Thousands)

Project Name & Location	Nature of Firm's Responsibility	Project Owner's Name & Address	Completion Date (actual or estimated)	Estimated Cost (In Thousands)	
				Entire Project	Work for Which Firm Was/Is Responsible
Inland Group – Multiple Facilities 2901 Butterfield Road Oak Brook, IL 60523	Visual Roof Condition Evaluations, Non-Destructive Moisture Surveys, and Roof Replacement Design Services	Inland Properties 2901 Butterfield Road Oak Brook, IL 60523	March 2006 to Present Current	\$ 238,000	\$ 238,000

In March of 2006, we contracted with Inland Group, to perform roof condition evaluations on 72 retail shopping center facilities (approximately 12,000,000 sq ft) located throughout the North and Southeastern United States. The initial group of inspections (72) were completed in a less than 120 days. We used three crews that traveled between projects within a geographic location and performed all of the required field investigation.

The crew leaders would then send hand written reports, field drawings and digital images on disk to our office for development of detailed database reports and AutoCAD roof plans. Since completion of the initial visual evaluations, we have also provided roof replacement design services on various projects. We have discussed providing our services for numerous other projects for the Inland Group and feel confident that we will be provided the opportunity to continue a long term relationship with their firm because of the quality of service and accuracy of information that we have provided to date.



- AL 2 Locations
- AL 3 Locations
- GA 6 Locations
- CT 8 Locations
- MA 7 Locations
- MD 10 Locations
- ME 2 Locations
- NC 2 Locations
- NH 1 Location
- NJ 3 Locations
- NY 34 Locations
- PA 17 Locations
- RI 5 Locations
- SC 4 Locations
- TN 5 Locations
- VA 4 Locations
- VT 1 Location
- 114 Locations**

